

Control Module: All Technical Service Bulletins Campaign - Low Range Lamp Falsely Indicated

FILE:

SERVICE: GROUP 00 OF SERVICE INFORMATION BINDER

PARTS: GROUP I OF INFORMATION - PARTS & ACCESSORIES BINDER

Campaign No. 1998060001

June 1998

TO: ALL MERCEDES-BENZ LIGHT TRUCK DEALERS

SUBJECT:

MODEL 163.154

LOW RANGE LAMP ERRONEOUSLY INDICATED

The transfer case control module in the affected vehicles must be replaced due to the possibility of the Low Range indicator lamp remaining illuminated after starting the vehicle at low ambient temperatures. Illumination of the lamp may be accompanied by transfer case or transmission control module Diagnostic Trouble Codes (DTC's). Replace the transfer case control module during the vehicle's next service visit.

Effective Serial Number Range

Model	Chassis End Number	
	From	To
163.154	A000001	A027490

Note:

There is no change in part number. The new component is identified by a GREEN part label. A green sticker will also be supplied with the new control module and the label must be installed on the inside of the fuse box lid above the spare fuses. This will be used as verification in the field that the replacement has been performed.

Immediately after receiving the dealer parts return report, the removed transfer case control module must be sent promptly to:

Mercedes-Benz U.S. International, Inc.
1 Mercedes Drive
Vance, AL 35490-9310
Attn. Door E 1.2 Warranty Receiving


Parts Information

Qty:	Part Name	Part Number
1	Control module	163 545 01 32

Warranty Claim Submission Information

Damage Code	Operation Number	Time (hrs.)	Model Indicator(s)
54 950 15	54 0000	1.0	01

Operation: Replace transfer case control module

 Cancel

 Capture